

BIAS SET PROCEDURE:
 1) ALL CONTROLS SET TO '0'.
 2) POWER ON/PLAY ON
 3) SET METER TO 200mVDC RANGE
 4) CONNECT METER RED LEAD TO TP1
 5) CONNECT METER BLACK LEAD TO TP2
 6) ADJUST BIAS TRIM POT TO 90mVDC (+/-5mVDC) ON METER

