


JCA50H Schematic – Includes Bias Settings

2.Block Diagram



### 3. Schematic Diagram

